

Error Code (depend on model version)

故障狀況 機種名	鍋溫熱敏電阻 OPENORSHORT	IGBT過熱保護	鍋具空燒保 護	高低電壓保 護	ACI保護	線盤銅線過熱 第2個 NTC保護	2小時自動關機	線盤盒斷線通訊 中斷	IR電路異常或環溫 高	I.COILOCP 及電路異常	爐心及人機介面通 訊異常	X:無振盪
Problems Models	NTC failure	Overheat	Empty Pan protection	Over voltage protection	ACI protection	Overheat (back-up protection)	Auto-off	Coil connection failure	IR sensor error	Circuit error	Display connection failure	Resonator failure
AB-14	-	-	-	-	-	-	-	-	-	-	-	-
HBB-10(BI-1000)	HE	E	F	H	U	-	-	-	-	-	-	-
	GE	E	F	H	U	-	-	A	-	-	-	-
HBB-10GERF HBB-17T/18T ABB-10/17/20/25T ATH-18T	E3	E7	E4	E6	E9	-	E2	-	-	-	-	-
ABB-18/25DE	E	F	H	-	-	-	-	-	-	-	-	-
CT-25 (ISM-25, (TT-2500) CW-25 (TTW-2500) CB-20(BI-2000R) CB-25(BI-2500R)	-	-	-	-	-	-	-	-	-	-	-	-
AB-20 (BI-2000NT) AB-25 (BI-2500NAT/ NBT)	E	F	H	U	-	-	-	-	-	-	-	-
BIB-X-2000/2500 ABIB-X-2000/2500	E	F	H	U	-	-	-	-	-	-	-	-
BMC-X-2500	E	-	E	-	-	-	-	-	-	-	-	-
BMC-X-2500N	E	-	E	-	-	-	-	E	-	-	-	-
CT-35/CB-35 ISM-35 /IE-35	E3	E7	E4	E6	E9	E5	-	-	-	-	-	-
CW-35 / IW-35	E3	E7	E4	E6	E9	E5	-	-	-	-	-	-
CT-70/CB-70	-	-	-	-	-	-	-	-	-	-	-	-
DT-35TE/TE1	E4	E7	E4	E6	-	E5	E2	-	E9	EA	Eb	EC
AT/AB/AW/ ABW-50A	E4	E7	E4	E5	E9	-	E2	-	-	EA	Eb	-

Error Sounds (Depend on model version)

故障 狀況機種名	鍋溫熱敏電阻OPENOR SHORT	IGBT過熱保護	鍋具空燒保護	高低電壓保護	ACI保護	線盤銅線過熱-第-個NTC保護	小時自動關機	線盤盒斷線-通訊中斷	IR電路異常或環溫高	I.COILOCP 及電路異常	爐心及人機介面通訊異常	X無振盪
Problems Models	NTC failure	Overheat	Empty Pan protection	Over voltage protection	ACI protection	Overheat (back-up protection)	Auto-off	Coil connection failure	IR sensor error	Circuit error	Display connection failure	Resonator failure
AB-14	1 long 2 short	1 long 7 short -	19 short 1 long	1 long 4 short	-	-	-	-	-	-	-	-
HBB-10(BI-1000) HE	1 long 2 short	1 long 7 short	19 short 1 long	1 long 4 short	-	-	-	-	-	-	-	-
HBB-10(BI-1000) GE	1 long 2 short	1 long 7 short	19 short 1 long	1 long 4 short	-	-	1 long	-	-	-	-	-
HBB-10GERF HBB-17T/18T ABB-10/17/20/25T ATH-18T	1 long 2 short	1 long 7 short	19 short 1 long	1 long 4 short	1 long 11 short	-	1 long	-	-	-	-	-
ABB-18/25DE	1 long 2 short	1 long 7 short	19 short 1 long	-	-	-	-	-	-	-	-	-
CT-25 (ISM-25 (TT-2500) CW-25 (TTW-2500) CB-20 (IE-20 (BI-2000F) CB-25 (BI-2500R)	1 long 2 short	1 long 7 short	19 short 1 long	1 long 4 short	-	-	-	-	-	-	-	-
AB-20 (BI-2000NT) AB-25 (BI-2500NAT/NBT)	1 long 2 short	1 long 7 short	19 short 1 long	1 long 4 short	-	-	-	-	-	-	-	-
BIB-X-2000/2500 ABIB-X-2000/2500	1 long 2 short	1 long 7 short	19 short 1 long	1 long 4 short	-	-	-	-	-	-	-	-
BMC-X-2500	1 long 4 short	-	19 short 1 long	1 long 4 short	-	-	-	-	-	-	-	-
BMC-X-2500N	1 long 4 short	-	19 short 1 long	1 long 4 short	-	-	-	1 long 4 short	-	-	-	-
CT-35/CB-35 ISM-35 / IE-35	1 long 2 short	1 long 7 short	19 short 1 long	1 long 4 short	1 long 11 short	1 long 15 short	-	-	-	-	-	-
CW-35 (IW-35)	1 long 2 short	1 long 7 short	19 short 1 long	1 long 4 short	1 long 11 short	1 long 15 short	-	-	-	-	-	-
CT-70/CB-70	1 long 2 short	1 long 7 short	19 short 1 long	1 long 4 short	1 long 11 short -	1 long 15 short	1 long	-	-	-	-	-
DT-35TE/TE1	18 short	1 long 2 short	18 short 1 long	1 long 4 short	-	3 short 1 long	1 long	-	2 long 1 short	2 long 2 short	1 long	1 long 1 short 3次
AT/AB/AW/ABW-50A	18 short	1 long 2 short	18 short	1 long 4 short	2 long 1 short	-	1 long	-	-	2 long 2 short	每30秒1 long	-